

APPENDIX C

Photo Documentation of Site

C-1

OTCR

au00

30291830




Superfund

1.0

ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE



No.: C-1

Subject Big River with mine tailing dust
rising from the pile.

Photographer

Robert Overfelt

Witness

Gene Gunn

Date/ Time

January 25, 1988 1030 hrs

Direction

North

No.: C-2

Subject

Area where mine
tailings slope
are in contact
with the Big River

Photographer

Robert Overfelt

Witness

Gene Gunn

Date/ Time

January 25, 1988
1030 hrs

Direction

North



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE

No.: C-3

Subject

Gap A from edge
of River after
filled

Photographer

Bob Overfelt

Witness


Gene Gunn

Date/ Time

January 25, 1988

Direction

West



No.: C-4

Subject

Wind fencing
Box configuration

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/ Time

January 25, 1988

1100 hrs

Direction

Southeast



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE

No.: C-5
Subject Wind

Fencing showing tail-
ings accumulation.

Photographer

Bob Overfelt

Witness

Gene Gunn


Date/ Time

January 25, 1988

1100 hrs

Direction

Southwest



No.: C-6
Subject Trees

Planted on north
side.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/ Time

January 25, 1988

1100 hrs

Direction

West



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE

No.: C-7

Subject

Trees planted on
north side.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date / Time

January 25, 1988

1100 hrs

Direction

Southwest



No.: C-8

Subject

"H" Gap filled

Photographer

Bob Overfelt

Witness

Gene Gunn

Date / Time

January 25, 1988

1120 hrs

Direction

Northeast



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE

No.: C-9

Subject

Trees & grass planted
on west side of pile
near gap I

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988

1130 hrs

Direction

Northeast



No.: C-10

Subject

Berm with Gap "I"
drainage pipe.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988 1200 hrs.

Direction

North



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE



No.: C-11

Subject Gap "I" drainage pipe from
Big River.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988 1230 hrs.

Direction

East

No.: C-12

Subject

West side where tailings
meet river.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988 1245 hrs.

Direction

Southwest



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE



No.: C-13

Subject

Cut back of river where tailings
meet river.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/ Time

January 25, 1988 1250 hrs.

Direction

Southeast

No.: C-14

Subject

Original drainage
structure.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/ Time

January 25, 1988 1300 hrs.

Direction

Southwest



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE



No.: C-15

Subject

Gap "E" showing tailings and
bedrock.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988 1320 hrs.

Direction

Southeast

No.: C-16

Subject

Gap "E" draining tail-
ings toward river.

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988 1325 hrs.

Direction

West



ECOLOGY & ENVIRONMENT, INC.
PHOTOGRAPHIC RECORD

SITE

No.: C-17

Subject

Dam above Gap "E"

Photographer

Bob Overfelt

Witness

Gene Gunn

Date/Time

January 25, 1988 1330 hrs.

Direction

Southwest



No.:

Subject

Photographer

Witness

Date/Time

Direction

END OF PHOTOGRAPHIC RECORD